



In-Plant Services, Inc.

380 Grandwood Blvd., Gray Court, South Carolina 29645
864.575.9987

- Vibration Analysis
- Balancing
- Laser Alignment
- Thermal Imaging



Customer Info

Equipment Info

customer	CF Sauer Co.	equipment	outside compressor area JM
location	Mauldin, SC	component	fuse block
date	August 23, 2002	data storage #	A07

Thermal Image Data

Priority ratings for under 600 volt electrical connections

reference	left fuse top			deg F	
reference temp	126.8 deg F		priority 1	> 135	immediate attention required
exception	center fuse top	x	priority 2	65 to 135	corrective measures required
exception temp	215.7 deg F		priority 3	20 to 65	schedule for PM
rise over ref	88.9 deg F		priority 4	1 to 20	document and follow-up
rise over amb	96.4 deg F				

Comments

pull all fuses, check for dirt or corrosion, loose or annealed clips, replace clip assembly as req.

